#### VISIBLE EMISSION NOTATIONS

Inspector:	laine 11	Gaecia				
Date of Inspection:	7/1/	15				
Shift: 1st Shift o	r 2nd Shift	Time:	5 AM	1		
luinit.		Visual Inspection Northwale			Colinarientes	
Visible Emission From	ı Shaker	ABINIORIMIAN Moe				
Visible Emission From Conveyor System	Discharge	NOR NOR				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NO	JAHONS					
Inspector:	emy Ha	win				
Date of Inspection:	11/15					
Shift: 1st Shift or	2nd Shift	Time:	630pm			
Unit		Visual linspection INORIMAL gr ABNORIMAL		E sinho	ients est de la company de la	
Visible Emission From Sl	naker	Norma/				
Visible Emission From D Conveyor System	scharge	Noting				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	ren	B and Toe		
Date of Inspection:	7	12/2015		
Shift: 1st Shift or	2nd Shift		712/2015	DC
i i Unit		Visual mulaspiediope		Comments
		<u>NORMÁL</u>	entral de la companya	
		o), <u>Aienióirim(A)</u> .		
Visible Emission From Sl	aker	Nor	#_successore	
Visible Emission From D Conveyor System	scharge	Nor		
		//		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTA	TIONS				
Inspector:					
	eremy Hardin				
Date of inspection:					
	2/13				
Shift: 1st Shift or 2	2nd Shift Time:	640 pm			
The Later Complete Company	Visuzi -	1 4 5 5	e (Colin)	nents	
	Inspection:				
	A SINDRIMALE		Application of the second		
The second second second			a profesional services		
	<u>ABNÖRMAL</u>				
					Company of the second second
Visible Emission From Shak					
	Normal				
Visible Emission From Disch	narge   '				
Conveyor System	Varma				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Darren I	3 andjoe				
Date of Inspection: 7/3/	15				
Shift: 1st Shift or 2nd Shift	Time:	6:00			
Mittell (1997)	Wisual		Compani	injus i garaga ka	The second secon
	lasoecilan Normali				
	or ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge					

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

Nor

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Conveyor System

VISIBLE EMISSION NOTATIONS	n //	<b>/</b>		
Inspector:	Salmest			
Date of Inspection:	3-15			
Shift: 1st Shift or 2nd Shift	t Time:	Spm		
Unit	Visual Inspection NORMAL		Comments	
	or <u>ABNORMÁL</u>	Hard State Control of the Control of		
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nos			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AIRIE EIMIRRI ÓIN NOTATIONS					
Inspector:	/				
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5200 pv			
.Unite	Msval   Inspection   <u>NoRMAL</u>   Or		<b>G</b> ganti	nenus/	
Visible Emission From Shaker	ABNORMALA SA				
Visible Emission From Discharge Conveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIONS	100%		_		
Inspector: Kulen H	Jokust				
Date of Inspection: 7/4/2	2015				
Shift: 1st Shift or 2nd Shift	: Time:	5:00p			
Unit	Visual Inspection:		e Paring Paring Co	Jeniancielous	
	<u>NORMAL</u>				
	io/ 4 Abnūrmal				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge					
Conveyor System	No-				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			,		
Inspector: Lime N GORG	CC(				
Date of Inspection: 7/5/2015					
Shift: 1st Shift or 2nd Shift	Time: -	5AM	•		
Unit	Visual Unspection			Comments	
	NORMAL 201				
	ABNORMAL	energies (Francisco)			
Visible Emission From Shaker	Nor	A Principal Conference on the			
Visible Emission From Discharge	N/				
Conveyor System	10R				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector:	lolar				
Date of Inspection: 7/5/	2015				•
Shift: 1st Shift or 2nd Shift	t Time:	5:00pm			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		. Con	nments	
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AISIBLE EMISSIO	MOTATIONS				
Inspector:	Paul	Ind			
Date of Inspection:	726-10	)			
Shift: 1st Shift	or 2nd Shift	Time:	5000		
Uin	iti	Misual Inspection I <u>NORMAL</u> OJ ASNORMAL		Commenus	
Visible Emission F	rom Shaker	NOV			
Visible Emission F Conveyor System		nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



VISIDEL LIVISSION NOTATIONS			<b>-</b>		
Inspector: Paul Lov	V		-		
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5,6			
Unit	. Visuali Jinsprædjom II		w co	innkantejands	
	I <u>MORMAL</u> Of				
	<u>ABNORIMAL</u>				
Visible Emission From Shaker	Val				
Visible Emission From Discharge					
Conveyor System	L 600				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VICIDIE ENVICCIONI NOTATIONIS

VISIBLE EMISSION NOT	ATIONS						
Inspector:	Soll	en B Adjo	C				
Date of Inspection:	Congression of the second	7-2-2013	ini kalandari kan kan kan kan kan pangan pangan kan kan kan kan kan kan kan kan kan k				
Shift: 1st Shift or	2nd Shift		6:00a	, ~~			
(Uppit		Visual Inspection Internal Internal			Cei	inlanterates Assistantial Institution	
Visible Emission From Sha	aker	Nor	<sub>and</sub> and a second	-			
Visible Emission From Dis Conveyor System	charge	Nas	, and companies.				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AISIBLE EINTISSION MOTATIONS			_		
Inspector:					
Date of Inspection:					•
Shift: (1st Shift) or 2nd Shift	Tíme:	5,00			
Unit	Misual Inspection <u>Mormal</u> Oj <u>Aemorimal</u>		Co	inimenus	
Visible Emission From Shaker	ren				
Visible Emission From Discharge Conveyor System	NOV				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)


١	nc	101	~	C 8	410	٠.	10			$\sim$ 4	- ^ -	-10	
١	v IS	וסו			///:	SC	ıU	IV	IV	UΙ	Ai	10	IV.

Inspecto	or:	da	ine N	Garcia						
Date of	Inspection:	7	18/15			-				
Shift:	1st Shift	or	2nd Shift	Time:	5An					
15.74	, Waji			Visual Inspection		10 P. LOG	, 18 G	a significação		
				TRIORIMAL	PALL CONTROL OF THE PARTY OF TH					
				oi <u>ABNORIMAI</u>				10		
Visible I	Emission Fr	om Sl	aker	Noa						
ì	Emission Fr or System	om D	scharge	Nor						

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AIZIBLE FIMIZZION NOTATIONZ					
Inspector:	lolad				
Date of Inspection: 718126	2/5				•
Shift: 1st Shift or 2nd Shift	Time:	5.00p			
Unit	Visual Linspections		Con	nments	
	<u>NORMAL</u>				
	ABNORMAL				
Visible Emission From Shaker	Nomal				
Visible Emission From Discharge					
Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)



AISIBLE FIMISSION NOTATIONS					
Inspector: Van Lad					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	Time:	5200			
Unit	Misual L. Inspection <u>NormAl</u>		iomunienus		
Visible Emission From Shaker	ABNORMAL.			78 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 —	
Visible Emission From Discharge	, N. D.				
Conveyor System	NOV				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EMISSION NOTATIONS				
Inspector: Rober M	dad			
Date of Inspection:	2015			•
Shift: 1st Shift or 2nd Shift	Time:	5:00pm		
Unit :: 4	Visual Inspection NORMAL 201 ABNORMAL		amments	
Visible Emission From Shaker	Normal	1455 E 17 (1455) - 4 (1456) E 1852 E 1852 E 1957 E 1852 E 185	And the control of th	
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION MOTATIONS				
Inspector: Rober Me	duel			
Date of Inspection:	2015			,
Shift: 1st Shift or 2nd Shift	Time:	5:00pm		
Unit	Msvali Inspection <u>NORMAL</u> FOI ABNORMAL		miments	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# VISIBLE EMISSION NOTATIONS

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

Inspecto	or: Sw	relko						
Date of	Inspection:	1 11 1	/					
Shift:	1st Shift or	2nd Shift	Tim	e: 5AM				
14.1	Unit		Wisdal Inspections			E (EGim)m		
			A NORMAL		100			

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up to shut down

AENORMA

nor

nor

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	Dam	ian	5alinas	25	
Date of Inspection	n: 7	-11-1	5		
Shift: 1st Shift	or	2nd Sh	ift	Time:	5pm

		<u></u>	
illinit Paga ang ang ang ang ang ang ang ang ang	Visual	" Comments	
	llátsjat∈crátota txl/otr¦ky/All		
grand of the second of the sec	3.44 (1201) 2001		
	VABNORMAL		
Visible Emission From Shaker	Nor		
Visible Emission From Discharge	4/		
Conveyor System	1000		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspect	tor:	Tе	remy Hardin	
Date of	f Inspection:	7-17	2-15	
Shift:	1st Shift	or	and Shift	Time: 6 00 am

		D DI WI			
uniča v se se politica v se	Visual		La Fig. Till Com	inicinies	
	i laspection :			Tarana and April 1985	
	<u>NORMAL</u>				
protection and the second second	es es contrata de la contrata del contrata de la contrata del contrata de la contrata del contrata de la contrata de la contrata de la contrata del contrata de la contrata del contrata de la contrata de la contrata del contrata de la contrata de la contrata de la contrata del contrata del contrata del contrata de la contrata de la contrata del contrata del contrat				
Visible Emission From Shaker	l '	1			
	NACMA				
Visible Emission From Discharge					
Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

inspector:		nich	Salinas	5,		
Date of In	spection:	7-	12-15			
Shift:	1st Shift	or	2nd Shift		Time:	5pm

J		•			
	Vigual	A Property	i waa saa ee aa Commen	iffS 1 (1)	2 Feb. 28 (28)
	inspection:				
	<u>NORMAL</u>				
and the second second second	congress.				
	ABNORMAL				Harris Barrier Barrier
Visible Emission From Shaker	Nor				
Visible Emission From Discharge		***************************************			
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge

Conveyor System

Inspect	tor:		Jeeny	Hardin				
Date o	f Inspection:		7/13/15					
Shift:	1st Shift	or	2nd Shift	Time:	630nm			
149.44	ប្រក្	L Santan	i in a second	Visual Inspection		Comments	ela esta de la companya de la compa	
100				NORMAL			Taken and the second	
				ABNORMAL				
Visible	Emission Fr	om Sl	haker					**************************************

Normal means emission's prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

Norma

Normal

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

A 1210 FF FIALISTICIA IACLE LICIA	VISIBLE	<b>EMISSION</b>	NO	TATIONS
-----------------------------------	---------	-----------------	----	---------

Visible Emission From Discharge

Conveyor System

Inspector: Dumian 5	alinas Tr							
Date of Inspection: 7-13-	15							
Shift: 1st Shift or 2nd Shift	ft Time:	5pm						
lunit 2	Visual			Commien	ţs			
	inspection NORMAL	Comment of the Commen					18 16 C	
	oir ABNIÓRIMAL	100						
Visible Emission From Shaker	ABNOTMAL	Sent a	t wark	order	fur	shaked	bout	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NO	TATIONS				
Inspector:	) La	ML.			
Date of Inspection:	13-15	)			
Shift: 1st Shift or	2nd Shift	Time:	5:00 AM		
Unit Time		Visual Linisjaectium NORMAL		Comments	
		MORNAL ABNORMAL			
Visible Emission From Sh	aker	ABNOT			
Visible Emission From Di	scharge	_			
Conveyor System		nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal missions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector:	nian Sa	linas Tr			
Date of Inspection:	7-14-15		geographic company (company god and artist and company are god and god god god god god god god god god go		•
Shift: 1st Shift	or 2nd Shif	t Time:	5pm		
. water		BATTERS OF THE STATE OF THE STA		Comments	
e de la companya de La companya de la co		NORMÁL			
W gg		ABNORMAL			
Visible Emission Fron	n Shaker	Nor			
Visible Emission Fron	n Discharge		Name.		
Conveyor System		Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTA	ATIONS		_		
Inspector:	LarC				
Date of Inspection:	1-14-18				
Shift: 1st Shift or	2nd Shift Time:	5700 Am			
Unit 4 december 1985	Visual Inspection NORMAL or ABNORMAL		Commen	its	
Visible Emission From Shal	ker Abnov				
Visible Emission From Disc Conveyor System	harge				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NO	IATIONS			_		
Inspector: Dam	ian S	alinas Ir			<b>.</b> *	
Date of Inspection:	7/18/19					
Shift: ast shift or	2nd Shift	Time:	Scopm			
design of Unit		Vilsual Magnection :			omments	
		<u> </u>				
eff of societies.		oa VABINIORIMAL				and the second
Visible Emission From Sh	aker	normal				
Visible Emission From Di	scharge	The public and the first section as a second fraction as a second fraction as a second fraction as a second				 
Conveyor System		romey				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NO	DIATIONS					
Inspector:	Selemy	Hardin				
Date of Inspection:	11615					
Shift: 1st Shift or	2nd-shift	Time:	6:00an			
llimit Anna a		Visual Inspection Normal		Comments.		
		g of ABNORMAL			Arthur San Carlotte (Carlotte (Carlo	
Visible Emission From S	haker	wermal		·		
Visible Emission From D Conveyor System	Discharge	Nomal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Damian S	Talinas Jr				
Date of Inspection: 7-16-15					•
Shift: 1st Shift or 2nd Shif	t Time:	5pm			
Unit Control of the C	Visual inspection NORMAL		Gomments		
	OF ABNORMAL		e en de en	property of the second	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	NOT				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOT	AHONS			<del></del> .			
Inspector: <u>Jeren</u>	ny Har	din					
Date of Inspection:	7/15						
Shift: 1st Shift or	2nd Shift	Time:	Socam				
Unit .		Visual Inspection			Comments	19 19 19 19 19 19 19 19 19 19 19 19 19 1	
The second of th		<u>Normal</u>					
		or <u>AENORMAL</u>		reserved (CE) (CE) (CE) (CE) (CE) (CE) (CE) (CE)			
Visible Emission From Sha	aker	Normal					
Visible Emission From Dis	charge	4101					
Conveyor System		Normen					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.1.12 SDS II Dally Visible Emissions Notations . . . .

VISIBL	E EMISSIOI	NO	TATIONS				
Inspect	or:	N	1	~ h	~		
		<u> </u>	mian	Salinas	) r		
Date of	Inspection:	4mas	1-17-10	<i>-</i>			
	1	(	-(/-(	)			
Shift:	1st Shift	or	2nd Shift		Time:	C = 20	

Unit	. Visual .		(Comp	nents	2.24
	រ វិតែនុទ្ធទីបីក្រែក្រ				
	<u>NORMÁL</u>				
	COLOR PERSON				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Nor	and the second			
Visible Emission From Discharge		defent.			
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: Jer	emy Har	din				
Date of Inspection:	1/18/15	ys.				
Shift: 1st Shift or	26d Shift	Time:	5:00am	{		
Lunit		Visual Inspection NORMAL TOTAL ABNORMAL		Col	mimenits	
Visible Emission From SI	haker	Normal				
Visible Emission From D Conveyor System	scharge	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge

Conveyor System

Inspector: Damia	n Salina	5 51				
Date of Inspection:	-18-15	and the state of the	Andrew Control of the			
Shift: 1st Shift or	2nd Shift	Time:	5pm			
lunrit Tarah		isual	State of the state	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	aninanasanas V	
	- <u>Mo</u>	tections R <u>MAL</u>	Lands and Comments		A STATE OF THE STA	
Fig. 1. Sec. 1	ABN	or et ÖRMÄL				
Visible Emission From Sha		/ _				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: Jaim	N Gorga			
Date of Inspection: 7/19	15			
Shift: 1st Shift or	2nd Shift Tim	e: 5AM		
Unit	Visual Inspection NORMAL 91 ABNORMAL		Zomments	
Visible Emission From Sha	ker NOR	**************************************		
Visible Emission From Disc Conveyor System	charge \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal missions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

## VISIBLE EMISSION NOTATIONS

Inspect	4	) <sub>ami</sub>	lan Salinga	Tr		
Date of	Inspection:		7-19-15			
Shift:	(1st Shift)	or	2nd Shift	Time:	Spm	

: Visual	The state of the s	Comr	nents		
				and the second s	
ABNORMAL .					
<i>a</i> / -					
/\/ <i>0</i> \/					
	· ·				
Nor					
	Inspection NORMAL LOI ABNORMAL	Inspection; NORMAL Lor J ABNORMAL	Inspection NORMAL Lot ABNORMAL	Inspection NORMAL  ABNORMAL	Inspection NORMAL Los ABNORMAL

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

D.1.12 SDS II Daily Visible Emissions Notations re. \_\_\_\_

VISIBLE EIVIISSION NO JATION	NS				
Inspector: Jame II Co	RCIG				
Date of Inspection: 7/20/1	5				
Shift: 1st Shift of 2nd S	hift Time:	5AM			
in Unit	Misual Inspection <u>NORMAL</u> I gr ABNORMAL		Gamri	Wents	
Visible Emission From Shaker	Nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE	<b>EMISSION I</b>	NOTATIONS
---------	-------------------	-----------

Inspector: Damian	Saling Dr				
Date of Inspection:	0-15	And the second section of the first of the first of the second section of the section of the second section of			
Shift: 1st Shift or 2nd	Shift Time:	5pm			
[Limit]	Visual Inspection NORMAL Top ABNORMAN		(Gor	mments	
Visible Emission From Shaker	Nor	9700000			
Visible Emission From Dischar Conveyor System	rge Noy	a/ '			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AIZIBLE FIMIZZION NOTATIONZ			<u></u>		
Inspector: Ted (	Conton				
Date of Inspection: 7/21/1	5	•			•
Shift: 1st Shift or 2nd Shift	Time:	5PM			
Uinti	Visual Inscrettion		. Cor	mments	
	<u>NORMAL</u>				
	ABNORMAL				
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	. /				
Conveyor System	No		http://milestaturpediatoriation/authorization/phinodelayattaturation/authorization/authorization/authorization		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVISSION NOTATIONS	4		-		
Inspector: Ted Coft	-m_				
Date of Inspection: 8/22/15					
Shift: (1st Shift or 2nd Shift	Time:	50M			
Unit	Mistral Inspection <u>(NormAll</u> or ABNORMAL			Pinimienus	
Visible Emission From Shaker	No		OCIDINATION OF THE PROPERTY OF		
Visible Emission From Discharge Conveyor System	Na		regional statistical program and accompany to the second		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION NOTATIONS		V-2	<del></del> -		
Inspector: Laime N	Cours				
Date of Inspection: 7/33/15					
Shift: 1st Shift or 2nd Shift	: Time:	JAM			
Unit 23	Visual/ Inspection NGRIMAL Or ABNORMAL			niments	
Visible Emission From Shaker	Non	#Source delination and a second a second and			
Visible Emission From Discharge Conveyor System	Non	razioni anteriore			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

## VISIBLE EMISSION NOTATIONS

Inspector:	Paul	Link				
Date of Inspection:		7-24-15	>			
Shift: 1st Shift or	2nd Shift	Time:	5:00 Am			
Unit		Visual Inspection Normal or Abnormal		Section 2.3	Comprens.	
Visible Emission From Sh	aker	abour.				
Visible Emission From Di Conveyor System	scharge	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	The state of the s					
Inspector: Damian Sa	linas Jr					
Date of Inspection: 7-28-15						
Shift: 1st Shift or 2nd Shift	Time:	SAM				
Unit 1	Visual Walinspection		Co H	omiments		
	<u>NORMAL</u> or ABNORMAL					
Visible Emission From Shaker	Nov		and the state of the		overland i sje greek van versje i seen kommen en groek een troch valend i stelle meet ke kommen stelle meet be	
Visible Emission From Discharge Conveyor System	Nov	*essere**				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VICIDIE ENVICEIONI NOTATIONE

D.1.12 SDS II Daily Visible Emissions Notations . ...

Shift: 1st Shift or 2nd shift Time: 5AM  Lunit Visual Comments  Inspection Normal  or ABNORMAL  Visible Emission From Shaker  Visible Emission From Shaker	VISIBLE EMISSION NOTATIONS	>		,		
Shift: 1st Shift or 2nd shift Time: 5AM  Lunit Visual Comments  Inspection Normal  or ABNORMAL  Visible Emission From Shaker  Visible Emission From Shaker	Inspector: Jaime N Gare	ia				
Unit   Visual   Comments   Inspection   In	Date of Inspection: 7/26/1	5				
Visible Emission From Shaker  Inspection  NORMAL  OI  ABMORMAL  ABMORMAL  ABMORMAL  ABMORMAL	Shift: 1st Shift or 2nd Shi	ft Time:	5 <sub>AM</sub>			
Visible Emission From Shaker  Visible Emission From Shaker	Unit			Co	omments	
Visible Emission From Shaker  Nor		NORMAL				
/VOR						
	Visible Emission From Shaker	Nor	- General constitution and the			
	Visible Emission From Discharge Conveyor System	Nos	Proceduration of Contraction			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual mariner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	< 1 /		Many .		
Inspector:	Salrainh				
Date of Inspection: 7-28-1	5				,
Shift: 1st Shift or 2nd Shift	) Time:	5 Am			
Unit	Visual Inspection		V-million Co	iniments	
	NORMAL .				
	or <u>Abnorimal</u>		Selection of the second		
Visible Emission From Shaker	Nor				
Visible Emission From Discharge	10				
Conveyor System	100y	-becomes-a-			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			I		
Inspector:	copton				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	Time:	5AN7			
Unit	Visual	Special 11 mg (12 mg) Talah Salah Sa	Park Sept. Property Co.	mments	
The state of the s	Inspection NORMAL	76.00			
	or				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Nor	stations up gringlish them who stages make providing the stations and providing the stations are stations as the stations are stations as the stations are stationary and are stationary are stationary and are stationary are stationary are stationary and are stationary are stationary are stationary and are stationary are stationary are stationary are stationary and are stationary are stationary are stationary are stationary are stationary and are stationary are stationary are stationary are stationary and are stationary are stationary are stationary are stationary are stationary and are stationary are stationary are stationary are stationary are stationary and are stationary and are stationary are stationary are stationary are stationary are stationary are stationary			
Visible Emission From Discharge	. /				
Conveyor System	No-				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE EIAIISSION MOTATIONS					
inspector: X ber X	lolal				
Date of Inspection: 7/28/					
Shift: 1st Shift or 2nd Shift	t Time:	Sicon			
Unit.	Visual Inspection P <u>NORMAL</u>		Co	mmenus	
	OF LEE				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Ted Co	enster				
Date of Inspection: 8/22/	54			•	
Shift: 1st Shift or 2nd Shift	t Time:	5AM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comm	ents	
Visible Emission From Shaker	No				
Visible Emission From Discharge Conveyor System	No	Charles september september september september sebes september sebes september sebes september sebes september			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# D.1.12 SDS II Daily Visible Emissions Notations Per Each Daylight Shift

AISIBLE EMISSION NOTATIONS			<b>-</b> .		
Inspector: Ted Confi	oten				
Date of Inspection:	)				
Shift: 1st Shift or 2nd Shift	Time:	5 Am			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Language en de la caractería de la carac	iments	
Visible Emission From Shaker	No	and the second s	Augustus and Augustus		
Visible Emission From Discharge Conveyor System	No-	Condession of the contract of			1

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

#### D.1.12 SDS II Daily Visible Emissions Notations Per Each Daylight Shift

AISIBLE FIMISSION NOTATIONS				
Inspector:	noten			
Date of Inspection: 7/3//	13			
Shift: 1st Shift or 2nd Shift	Time:	SAM		
Unit	Visual Inspection <u>NORMAL</u> Or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Na			
Visible Emission From Discharge Conveyor System	Nac			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

### D.1.12 SDS II Daily Visible Emissions Notations Per Each Daylight Shift

VISIBLE EMISSION NOTATIONS					
Inspector:	Idel				
Date of Inspection: 7/31	115				
Shift: 1st Shift or 2nd Shift	Time:	5,00pm			
Unit	Visuali W Inspections III		Con	mmens.	
	<u>NORMAL</u>				
	<u>ABNORMAL</u>				
Visible Emission From Shaker	Normal				
Visible Emission From Discharge	<b>1</b>				
Conve <b>y</b> or System	Normal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)